

# PAXTON LIGHT DEPARTMENT

## New Service Requirements

- A service application must be filled out at the Light Department. A copy of your driver's license or other form of ID is required.
- An electric permit must be obtained from the Town of Paxton Wiring Inspector.
- All services must be inspected before energizing.
- All overhead services will be connected using Light Department connectors and by Light Department employees.
- All wires from the pole to the service cable will be purchased from the Light Department and installed by Light Department employees.
- All meters must have a disconnect.

To schedule an inspection or to set up an appointment, call General Foreman, Tim White, (774)502-5796 or email: [twhite@paxtonlight.com](mailto:twhite@paxtonlight.com)

## New Underground Services (URD)

- URD services must use 2 ½" Sch 40 Pipe with Sch 80 at the pole for a riser. All pipe crossing a roadway or driveway must be in Sch 80 and concrete.
- All trenches will be inspected by a Light Department employee before backfilling.
- Meter sockets will have a disconnect along with an expansion coupling.

### Trench Specifications

All trenches must be 42" deep with 6" sand on the bottom, another 12" of sand on top of the pipe with caution tape, then backfill.

